





MECHANICAL LOCK PANEL PROFILE



STRIATIONS OR FLAT PANEL

*OIL CANNING IS NOT A CAUSE FOR REJECTION